

### **HSS Safety Culture Extent of Condition Evaluations**

HSS was tasked to perform these evaluations in response to Defense Nuclear Facilities Safety Board (DNFSB) Recommendation 2011-1, Safety Culture at the Waste Treatment and Immobilization Plant, which indicated a chilled atmosphere adverse to safety at WTP and management suppression of technical dissent. The DNFSB recommended that DOE perform an extent-of-condition review to determine whether these safety culture weaknesses were limited to WTP, or whether they were evident at other DOE/National Nuclear Security Administration (NNSA) sites or facilities.